Job: TRANSMISSION OUTPUT SEAL (WESTERN AUTH 9084721) (Continued)

Job For: 2006 BMW R1200GS WB10317A86ZR41015

Labor

Description

Job Code

Technician

Quantity

Line Total

RENEW TRANS OUTPUT SHAFT SEAL 2312078

RYAN HILDEBRAND

1.54 Hours

\$149.38

Labor Subtotal

\$149.38

Recommendations

Resolution

TECH REPLACED TRANS OUTPUT SEAL

Job Subtotal

\$165.30

Job: CLUTCH SLAVE CYLINDER (WESTERN AUTH 9084721)

Job For: 2006 BMW R1200GS WB10317A86ZR41015

Description

C/S THERE IS A LEAK AROUND THE CLUTCH SLAVE CYLINDER.

| Pa | rte |
|----|-----|
| | |

| Part Number | Quantity | Description | | Each Price | Extension |
|----------------------|----------|---------------------------|---------------------|----------------|------------|
| 21527724542 | 1 | OUTPUT CYLI | NDER CLUTCH | \$151.51 | \$151.51 |
| 07119963072.5 | 2 | SEAL RING/FORCE QTY. 25 | | \$0.89 | \$1.78 |
| 23127705085.5 | 1 | SHAFT SEAL, | CLUTCH/FORCE QTY. 4 | \$13.05 | \$13.05 |
| 07510398494.5 | 1 | MINERAL OIL/FORCE QTY. 12 | | \$4.50 | \$4.50 |
| , | | | | Parts Subtotal | \$170.84 |
| Labor Description | | Job Code | Technician | Quantity | Line Total |
| RENEW CLUTCH SLAVE | CYLINDER | 2152013 | RYAN HILDEBRAND | 0.28 Hours | \$27.16 |
| BLEED CLUTCH SYSTEM | 1 | 2152005 | RYAN HILDEBRAND | 0.28 Hours | \$27.16 |
| RENEW SEAL | | 2312023 | RYAN HILDEBRAND | 1.12 Hours | \$108.64 |
| | | | | Labor Subtotal | \$162.96 |

Recommendations

Resolution

TECH REPLACED SLAVE CYLINDER

Job Subtotal

\$333.80

Customer Job Totals

Parts \$205.54 Labor \$333.51 \$4.00 Other \$543.05 **Total of Customer Jobs**

Repair Order Subtotal

\$543.05

Discounts Given Parts Discount:

\$3.40

Sales Tax \$16.96

Repair Order Total \$560.01

Previous Deposits \$45.50

Total Amount Due \$514.51

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. IT IS UNDERSTOOD THAT THIS COMPANY ASSUMES NO RESPONSIBILITY FOR LOSS, OR DAMAGE BY THEFT OR FIRE TO VEHICLES PLACED WITH THEM FOR STORAGE, SALE, REPAIR OR WHILE ROAD TESTING. DUE TO PROGRAM ERROR, DISREGARD HRS/QTY HEADING ABOVE \$75.00 PER DAY STORAGE FEE WILL BE CHARGED BEGINNING 5 DAYS AFTER NOTIFICATION OF COMPLETION OF REPAIRS.

| SIGNED | |
|-------------|---|
| ACKNOWLEDGE | NOTICE AND ORAL APPROVAL OF INCREASE IN THE PRICE |
| SIGNED | |
| | B.A.R. # AM129453 EPA # CAL 000271714 |
| | RETURN OLD PARTS YES NO |