

A&S MOTORCYCLE PARTS,

1125A Orlando Ave.
Roseville, CA 95661-
(916) 726-7334

Repair Order Invoice

| | |
|--------------------------|--------------------------|
| R/O Number: 999073644 | Invoice Number: 99834480 |
| Date In: 3/8/2014 | Today Date: 3/13/2014 |
| Date Promised: 3/8/2014 | Date Closed: 3/11/2014 |
| Cashier: CLINTON RIGGINS | |

Repair Order For:

Description: 001

Units For This Repair Order

Service Writer: CLINTON RIGGINS

| Year | Make | Model | VIN/Serial No. | Plate | Key Board | Miles In/Out |
|------|------|---------|-------------------|-------|-----------|---------------|
| 2009 | BMW | K1300GT | WB10539019ZV96537 | | 1183 | 24348 / 24356 |

Job: * INSPECTION II SERVICE

Job For: 2009 BMW K1300GT WB10539019ZV96537

Description

CUSTOMER STATES HE WOULD LIKE TO HAVE THE INSPECTION II SERVICE PERFORMED.

THE LABOR TIME FOR THE "ADJUSTMENT" MAY NOT BE NEEDED IF ALL VALVES ARE WITHIN BMW SPECIFICATIONS

IN THE CASE THAT ANY AFTERMARKET ACCESSORIES WILL NEED TO BE REMOVED AND REINSTALLED TO ALLOW FOR THE SERVICE TO BE PERFORMED, ADDITIONAL LABOR WILL BE CHARGED BASED ON THE INCREASED TIME NECESSARY TO COMPLETE THE SERVICE

Parts

| Part Number | Quantity | Description | Each Price | Extension |
|---------------|----------|---------------------------------|------------|-----------|
| CLEANER | 5 | CHEMICALS AND CLEANERS | \$1.00 | \$5.00 |
| 13717713428 | 1 | AIR FILTER ELEMENT | \$43.12 | \$43.12 |
| 81220142156 | 1 | BRAKE FLUID 355 M/FORCE QTY. 12 | \$4.55 | \$4.55 |
| 11427721779 | 1 | OIL FILTER/FORCE QTY. 10 | \$16.59 | \$16.59 |
| CASTROL 5/40 | 4 | CASTROL 5/40 SYN DRUM | \$11.50 | \$46.00 |
| CWS.1 | 1 | CRUSH WASHER / ZIP TIES / MISC | \$1.00 | \$1.00 |
| CASTROL 75/90 | 1 | CASTROL 75W90 SYN (DRUM OIL) | \$10.42 | \$10.42 |

Parts Subtotal \$126.68

Labor

| Description | Job Code | Technician | Line Total |
|---------------------------------|----------|-----------------|------------|
| INSPECTION II | 0000111 | RYAN HILDEBRAND | \$71.40 |
| read fault code memory | | RYAN HILDEBRAND | \$0.00 |
| *oil change & filter change | 1100609 | RYAN HILDEBRAND | \$57.12 |
| *replace air filter 12k | 1372505 | RYAN HILDEBRAND | \$42.84 |
| *final drive fluid 2yr 12k | 3300501 | RYAN HILDEBRAND | \$57.12 |
| visually inspect brake lines | | RYAN HILDEBRAND | \$0.00 |
| ck frt. brake pads & disc w ear | | RYAN HILDEBRAND | \$0.00 |
| *chg brake fluid 2yrs | 3400010 | RYAN HILDEBRAND | \$114.24 |

Job: * INSPECTION II SERVICE (Continued)
Job For: 2009 BMW K1300GT WB10539019ZV96537

Labor (Continued)

| Description | Job Code | Technician | Line Total |
|-------------------------------|----------|-----------------|------------|
| ck clutch system | | RYAN HILDEBRAND | \$0.00 |
| ck throttle cable play | | RYAN HILDEBRAND | \$0.00 |
| ck coolant level | | RYAN HILDEBRAND | \$0.00 |
| ck tire pressure & depth | | RYAN HILDEBRAND | \$0.00 |
| ck side stand movement | | RYAN HILDEBRAND | \$0.00 |
| ck all signal lights | | RYAN HILDEBRAND | \$0.00 |
| function test engine start up | | RYAN HILDEBRAND | \$0.00 |
| *lube ball joint clamp | 1821510 | RYAN HILDEBRAND | \$28.56 |
| *check relay lever 2yrs | 3353732 | RYAN HILDEBRAND | \$14.28 |
| final inspecton/test ride | | RYAN HILDEBRAND | \$0.00 |
| read fault code memory | | RYAN HILDEBRAND | \$0.00 |
| set service due date | | RYAN HILDEBRAND | \$0.00 |
| ck battery charge state | | RYAN HILDEBRAND | \$0.00 |
| confirm service inboard comp. | | RYAN HILDEBRAND | \$0.00 |
| (*) BILLED AS SEPARATE ITMES | | RYAN HILDEBRAND | \$0.00 |
| ADD. LABOR FOR ACC.REMOVAL/WT | | RYAN HILDEBRAND | \$0.00 |

Labor Subtotal \$385.56

Recommendations

Resolution

tech performed the inspection II service

Other Charges
 Hazmat Fee \$4.00

Job Subtotal \$516.24

Job: 00 11 31 00 00 RETROFIT TIMING CHAIN GUIDE (Warranty Claim Number: 73644)
Job For: 2009 BMW K1300GT WB10539019ZV96537

Description

PERFORM BULLETIN #11 004 12 017 RETROFIT TIMING CHAIN GUIDE.

*****USE ONLY ONE LABOR CODE**NOT BOTH*****

Parts

| Part Number | Quantity | Description | Each Price | Extension |
|-------------|----------|---------------------------|------------|-----------|
| 11318526932 | 1 | CHAIN TOOTH-JUMP GUARD | Warranty | Warranty |
| 11147727974 | 1 | GASKET ENGINE COVER RIGHT | Warranty | Warranty |
| 11137676132 | 17 | ISA SCREW/FORCE QTY. 10 | Warranty | Warranty |
| 11147678478 | 3 | SCREW/FORCE QTY. 10 | Warranty | Warranty |

Parts Subtotal Warranty

Labor

| Description | Job Code | Technician | Line Total |
|----------------------------|----------|-----------------|------------|
| RETROFIT CHAIN GUIDE | 1111515 | RYAN HILDEBRAND | Warranty |
| RENEW GUIDE @ VALVE ADJUST | 0060658 | RYAN HILDEBRAND | Warranty |

Labor Subtotal Warranty

Recommendations

Resolution

tech performed recall

Job Subtotal Warranty

Job: LEFT OFF THROTTLE & BIKE DIES(WESTERN SERVICE)
Job For: 2009 BMW K1300GT WB10539019ZV96537

Description

CUSTOMER STATES THAT THE BIKE WILL DIE 25% OF THE TIME WHEN LET OFF THROTTLE OR AT STOPS.

** BIKE IS UNDER WESTERN WARRANTY ***

ALSO WHEN COASTING DOWNHILL AND OFF THROTTLE IT TAKES TIME FOR BIKE TO MATCH THROTTLE WHEN BACK ON.

*** PLEASE INSPECT AND ADVISE

Labor

| Description | Job Code | Technician | Line Total |
|-----------------------|----------|-----------------|---------------|
| INSPECT & ADVISE | | RYAN HILDEBRAND | \$0.00 |
| Labor Subtotal | | | \$0.00 |

Recommendations

Resolution

tech test rode bike on freeway and in stop and go traffic. no issues found at this time

Job Subtotal **\$0.00**

Customer Job Totals

| | |
|-------|----------|
| Parts | \$126.68 |
| Labor | \$385.56 |
| Other | \$4.00 |

Total of Customer Jobs **\$516.24**

Repair Order Subtotal **\$516.24**

Sales Tax **\$9.50**

Repair Order Total **\$525.74**

Total Amount Due **\$525.74**

Tendered: SERVICE CR **\$525.74**

Change Due **\$0.00**

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. IT IS UNDERSTOOD THAT THIS COMPANY ASSUMES NO RESPONSIBILITY FOR LOSS, OR DAMAGE BY THEFT OR FIRE TO VEHICLES PLACED WITH THEM FOR STORAGE, SALE, REPAIR OR WHILE ROAD TESTING. DUE TO PROGRAM ERROR, DISREGARD THE HRS/QTY HEADING ABOVE \$75.00 PER DAY STORAGE FEE WILL BE CHARGED BEGINNING 5 DAYS AFTER NOTIFICATION OF COMPLETION OF REPAIRS.

SIGNED _____

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF INCREASE IN THE PRICE.

SIGNED _____

B.A.R. # AM129453 EPA # CAL 000271714

RETURN OLD PARTS. YES NO

THE FOLLOWING APPLIES TO CALIFORNIA MOTORCYCLE OWNERS WHERE REPAIRS INVOLVE INSTALLATION OF MOTORCYCLE PARTS: A buyer of this product in California has the right to have this product serviced or repaired during the warranty period. The warranty period will be extended for the number of whole days that the product has been out of the buyer's hands for warranty repairs. If a defect exists within the warranty period, the warranty will not expire until the defect has been fixed. The warranty period will also be extended if the warranty repairs have not been performed due to delays caused by circumstances beyond the control of the buyer, or if the warranty repairs did not remedy the defect and the buyer notifies the manufacturer or seller of the failure of the repairs within 60 days after they were completed. If, after a reasonable number of attempts, the defect has not been fixed, the buyer may return this product for a replacement or a refund subject, in either case, to a deduction of a reasonable charge for usage. This time extension does not affect the protections or remedies the buyer has under other laws. SONG-BEVERLY WARRANTY ACT

A&S Powersports

Multi-Point Inspection

Name: _____

Customer Concerns:



Make: _____ Model: _____

Mileage: 24349 Lic Plate #: 20E3902

VIN# 2V96537

Customer Signature: _____

Mark Visible Damage



Front Tire Tread Rear

- 5mm or Greater
- 3mm to 4mm
- Needs Replacement

Front PSI: @ _____ Set To: 40

Rear PSI: @ _____ Set To: 42

Brakes

- | | OK | Attention | Replace |
|-------------|-------------------------------------|--------------------------|--------------------------|
| Front Pads | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Front Discs | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Rear Pads | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Rear Discs | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Fluids

- | | OK | Replace |
|-------------------|-------------------------------------|--------------------------|
| Engine Oil | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Transmission Oil | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Front Brake Fluid | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Rear Brake Fluid | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Clutch Fluid | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Coolant | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Bolts Torqued

- Front Calipers Front Wheel
- Rear Caliper Rear Wheel
- Oil Drain

Lights

- | | OK | Replace |
|--------------|-------------------------------------|--------------------------|
| Headlight | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Tail Light | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Brake Light | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Turn Signals | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Other Lights | <input type="checkbox"/> | <input type="checkbox"/> |

Leaks

- | | OK | Replace |
|--------------|-------------------------------------|--------------------------|
| Engine | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Transmission | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Final Drive | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Coolant | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Forks | <input type="checkbox"/> | <input type="checkbox"/> |
| Fuel | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Additional Checks

- | | OK | Attention | Replace |
|---------------|-------------------------------------|--------------------------|--------------------------|
| Belts / Chain | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Horn | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Battery | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Wheels | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Cables | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Hoses | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Clock Set | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

(Applicable)

(Not Applicable)

Service Mileage Reset

Service Due Date Reset

Technician Signature RY