

# MULTI-POINT SAFETY INSPECTION

Name: [REDACTED]

Model: R1100GS

A. Good    B. May require future attention    C. Requires immediate attention

A, B, OR C

A Tires:    Pressure:    Front 34 PSI    Rear 36 PSI  
                  Tread depth:    5.15 mm    3.05 mm

A Fluids:    Engine oil /    Brake fluid Ft. /  
                  Coolant N/A    Rr. /

A Lights:    Headlight /    Rt Signal /    Brake X  
                  Tail light /    Lt Signal /    Horn /

A Brakes:    Front 85 %Remaining    Rear 95 %Remaining

A Torque:    Front and rear caliper bolts: /    /  
                  Front and rear wheel mount bolts: /    /  
                  Oil drain plug: /  
                  Engine: /    Trans: /    Final drive: /

A Leaks:    Engine:           Forks:           Final drive         
                  Fuel:           Coolant:       

### Additional Notes:

Rear brake light switch is not functioning. Recommend  
replace as soon as possible.

(working now)  
AE

Tech. # 111